


**GENWAL**  
RESOURCES, INC.P.O. Box 1420 • 195 North 100 West • Huntington, Utah 84528  
Telephone (801) 687-9813 • Fax (801) 687-9784

June 22, 1995

Mr. Daron R. Haddock  
Permit Supervisor  
Division of Oil, Gas and Mining  
3 Triad Center  
355 West North Temple  
Salt Lake City, Utah 84180-1203



RE: SAE plan deficiencies withdrawal of application for minor amendment, Crandall Canyon Mine, ACT/015/032-94E, Folder #3, Emery County, Utah.

#3

*Copy sent to Daron  
ad Joe*

Dear Daron:


Genwal Resources, Inc. is requesting a withdrawal of the minor amendment associated with SAE's #5, #6, and #7. At this time Genwal is collecting additional data associated with the physical characteristics of the soil. A new request for a minor amendment associated with the ASCA's and SAE's will be submitted later this fall.

At this time the three areas fall under the ASCA guidelines because:

1. The topsoil stockpiles are stabilized and non-eroding with a very good vegetative cover and have been for several years.
2. The topsoil stockpiles are protected from excessive offsite erosion by curbing, siltfences and strawbale dikes.

I appreciate the opportunity to work with you on this project. I also wish to express gratitude for the ability to work closely with your staff on this matter.

Sincerely,



Randolph B. Gainer, PG.  
Environmental Manager